

58 | 59

Renew Sec. Cor. 517 | 516 T255 R3W

Fd. G.L.O. BRSS C 2<sup>d</sup> MKd. T255 R3W

58 | 59  
517 | 516

1944 " with steel fence post

set along side of BT's as follows -

orig 30 now 36" Fir S, 65° E, 21 <sup>8</sup>/<sub>8</sub> ft.

2 live shows old scar - we do not open

1944 Resurvey 12" now 21" R. cedar N. 50° E, 56 <sup>3</sup>/<sub>8</sub> ft.

show "T255 R3W 59 BT" on partially healed blaze.

1944 Resurvey 10" now 14" <sup>Fir</sup> 560° W, 67 <sup>3</sup>/<sub>8</sub> ft.

Shows good scar - we do not open.

1944 Resurvey 6" now 11" Red cedar N. 29° W, 33 <sup>0</sup>/<sub>8</sub> ft.

healed blaze - we do not open - roots

wrapped around old log, we mark new

BT's -

26" R. cedar S, 56° E, 22 <sup>0</sup>/<sub>8</sub> ft.

Mkd. "T255 R3W 516 CS BT"

9" Hemlock N, 37° W, 16 <sup>2</sup>/<sub>8</sub> ft.

Mkd. "T255 R3W 58 CS BT"

Cor. lies on bench between small

spurs.

FILED

RECEIVED

August 5, 1966

U. S. D. I.

AUG

5 1966  
J.H.

COUNTY SURVEYOR

WASCO COUNTY, ORE.

\* 99

C. S. File No. 127-70