

Renew $\frac{1}{4}$ 510 | 511 ~~255~~ R3W

Fd. G.L.O. BR755 C2P MKd. $\frac{1}{4}$ 510 | 511 1943"
with Steel fence post set along side
& STUMPS of BTs as follows -

orig. 60" Now 60" Fir S. 48° E. 5 $\frac{3}{4}$ ft.
Recorded as S. 48° W. - Shows "B.T." scribe
on Burned face - Now STUMP.

orig. 30" Now 30" Hemlock N. 37° W. 13 $\frac{3}{4}$ ft.
Burned - No scribe fd. - STUMP

1943 Resurvey 42" Now 43" Fir S. 35° W. 34 $\frac{3}{4}$ ft.
Now Burned STUMP - AXE MKs - NO scribe fd.
we MK. New BTs -

5" D. Fir N. 65° W. 41 $\frac{6}{8}$ ft.
MKd. $\frac{1}{4}$ 510 CS BT"

5" D. Fir N. 36° E. 28 $\frac{3}{4}$ ft.
MKd. $\frac{1}{4}$ 511 CS BT"

COR. lies on top of rounded SPUR
Sloping South.

August 8, 1966

FILED

V.R.T.

J.B.

RECEIVED

H.

AUG 8 1966

V. B. Tracy

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

*#101

C. S. File No. 5467-72