

Renew $\frac{1}{4}$ 59/510 T245 R3W

Fd. O.B.T.S 25 follows -

orig. 7" Now 9" Yew N, 20° E. 10⁶ft.

2 live - Bent over & Blaze Rotted away

No scribe fd.

orig. 24" Now 37" Hemlock N, 80° W. 7²ft.

2 live - we open & find scribe & Reverse.

We use face measurements on O.B.T.S -

Set 1" I.P. & BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1967 T245

$\frac{1}{4}$ 59/510 R3W" & MK. new B.T.S -

6" Hemlock S, 58° W, 22⁶ft.

Mkd. " $\frac{1}{4}$ 59 CS BT"

14" Hemlock S, 64° E. 25^L ft.

Mkd. " $\frac{1}{4}$ 510 CS BT"

This COR. Lies westerly slope
in small stand off old growth
Timber.

Sept 12, 1967

V.R.T.

J.H.

D.W.

~~V.R.T. Gray~~

0
457

O.W. J.W.B.

C.S. File No. 54/27

-82