

Renew  $\frac{1}{4}$  55/54 T245 R3W

Fd. 1950 B.T. 25 follows -

9" Now 14" Hemlock N,  $75\frac{1}{4}^{\circ}$  E, 50<sup>±</sup> ft.

Now Stump - Brass Buried - we open  
& find scribe mks.  $\frac{1}{4}$ " No Trace

S.W. B.T. or Brass cap called for.

However, Brass cap may be much  
deeper in dirt from large root  
wad. set 1" I.P. & Brass cap MKd.

"COUNTY SURVEYOR'S OFFICE

1967 T245  $\frac{1}{4}$  55/54 R3W" with

Steel fence Post 6<sup>±</sup> ft. Long set  
along side. MK. New B.T.s -

20" Hemlock Stump S, 29<sup>±</sup> ° E, 32<sup>±</sup> ft.

Mkd.  $\frac{1}{4}$  55 CS BT"

10" Hemlock S, 27 ° W, 46<sup>±</sup> ft.

Mkd.  $\frac{1}{4}$  54 CS BT"

This cor. lies on gentle  
Easterly slope 100 ft. west of  
old log access Road.

Sept 22, 1967

V.R.T.  
J.H.  
D.W.

V.R. Tracy

O.K. J.W.B.

O.K. G.S. Flansburg 54/27