

Fd. Sec. Cor. $\frac{510}{514}$ T24SR3W

We find No Trace of Orig. Cor. Tree
OR B.T.S. - We do find 2nd steel pipe
& Weyerhaeuser method B.T.S. as follows -

16" D. Fir S. 17° W. 28 ± ft "W" Nail & Tag.

70" D. Fir Stump N. 75° W. 65 ± ft.

"W" Nail & Brass plate & Tag.

48" D. Fir Stumps N. 3° W. 35 ± ft.

"W" Nail & Plate & Tag.

14" Hemlock S. 42° E. 38 ± ft.

"W" & Tag.

Dec. 1, 1967

~~W.R.T. J.H. V.P.~~

~~W.R.T. King~~

DIETZGEN NO. 385-6

N.F. 24-3

$\frac{1}{4} \frac{53}{510}$ Logged ✓

**FILED
RECEIVED**

NOV 30 1967

**COUNTY SURVEYOR
DOUGLAS COUNTY**

CS 54/27-97

RS. 1.