

Renew $\frac{1}{4}$ COR. 526⁺525 T23SR2W

Fd. CBTs as follows -

ORIG. 40" Now 48" FIR N. 63°E, 5³ ft.
2 live - shows good SCOR.

ORIG. 40" Now 40" FIR S, 75°W, 13³ ft.

Now 50g - "1/4 S BT" scribe visible
on unhealed Blazes - Tree Badly
decayed - we do not find cor.

stone. 2⁺ COR point set 1"

I.P. & BRASS CAP MKD. "COUNTY
SURVEYOR'S OFFICE 1969

T235 $\frac{1}{4}$ 526/525 R2W" & MK.

New BTs -

12" Hemlock N, 42°E, 19⁶ ft.

Mkd. "1/4 S25 DCS BT"

12" Hemlock S, 40°W, 49⁶ ft.

Mkd. "1/4 S26 DCS BT"

This COR. Lies on Very
steep NW Slope in Rhododendron
BRUSH.

July 9, 1969

KRT.
J.G.H.
V.D.P.

J.R. Tracy

#1 P.

C.S. File No. 52/27¹⁰⁴ 104
D.K.
1/2 W 13