

Review $\frac{1}{4}$ cor. $\frac{529}{532}$ T235 R2W

Fd. OBJs as follows -

ORIG. 20" now 26" N, 30°W, 23 $\frac{8}{10}$ ft.

BROKEN OFF - " $\frac{1}{4}$ 5" scribe visible on
Log & Reverse "BT" on Remains
of Stump.

ORIG. 40" now 48" F.R.S., 45°W, 21 $\frac{1}{2}$ ft.

2 live - Log of Turnout lying over
Blaze - No MKd. Stone Fd. - 2T

COR. point set 1" I.P. & BRASS cap

Mkd. COUNTY SURVEYOR'S OFFICE

1969 T235 $\frac{1}{4}$ $\frac{529}{532}$ R2W" & MK

New BTs -

13" Hemlock N. 27°E, 35 $\frac{5}{10}$ ft.

Mkd. " $\frac{1}{4}$ 5 29 CS BT"

15" cedar S. 33°E, 24 $\frac{3}{10}$ ft.

Mkd. " $\frac{1}{4}$ 5 32 CS BT"

This cor. lies on very steep
westerly slope.

July 23, 1969

V.R.T.

J.G.H.

V.D.P.

V.G.T. Ray

+26

U.S. File No.

9.K.
W 113.
54/27-113