

Review $\frac{1}{4}$ 59/510 T255 R2W

Fd. 1962 Cad. Brass cap in place
& properly MKD. with orig cor.
stone MKD " $\frac{1}{4}$ " set on ON South
side. B.T.s as follows -

Orig. 8" Now 12" Yew N. 75° W. 13° ft.

BROKEN - Dead - No scribe

182 27" Now 28" ^{HEMLOCK} N. 26° W. 66° ft.

alive - good - scribe " $\frac{1}{4}$ 59 BT" visible

1962 32" cedar S. $45\frac{1}{2}^{\circ}$ E. 60° ft.

Now SNAG - Bent over by large fir

Log - We MARK. New BT. -

36" cedar N. 1° E. 20° ft.

scribed " $\frac{1}{4}$ 510 CS BT"

Old Line tree North 135° ft.

Now 80 ft. High SNAG - Notches
on N. & S. sides visible.

This cor. lies on very steep,
southerly slope in canyon.

June 26, 1972

V. R. T.
L. E. M.
D. G. S.

V. R. Tracy

O.K.

[Signature]

1490

C.S. File No. 54/271

127