

Renew $\frac{1}{4}$ $\frac{534}{53}$ T235 R2W

Fd. cor. ~~Sw~~ with partial " $\frac{1}{4}$ " 4
chipped off & O.B.T.s as follows
(1894 Resurvey)

20" Now 30" Hemlock S. 76 $\frac{1}{2}$ ° E. 12 $\frac{5}{8}$ ft.
2 live - shows good scar

18" Now 22" Hemlock N. 4° W. 5 $\frac{3}{8}$ ft.

Dead - " $\frac{1}{4}$ 5 BT" scribe visible
on unhealed blaze - 2nd cor.

point in place of cor. stone
set 1" I.P. & Brass cap MKd.

"COUNTY SURVEYORS OFFICE
1969 T235 $\frac{1}{4}$ $\frac{534}{53}$ T245 R2W"

& Reset stone along side,
MARK New B.T.s -

8" Hemlock N. 22° W. 49 $\frac{1}{4}$ ft.

Mkd. " $\frac{1}{4}$ S 34 CS BT"

12" Hemlock S 82° W. 28 $\frac{1}{4}$ ft.

Mkd. " $\frac{1}{4}$ S 3 CS BT"

This cor. lies approx 160 ft
west of creek 2 ft. wide
course S.W.

Jelly 29, 1969

VRT
J & H
VDP

A. P. Tray
#270 $\frac{723-2}{56}$

C. S. File No. 54/27-164
O.K. J.W.B.