

Renew Closing Cor. <sup>R3W</sup> 513 <sup>57</sup>/<sub>518</sub> T25 R2W  
Fd. G.L.O. Brass Cap MKd "T255 513  
R3W <sup>57</sup>/<sub>518</sub> cc T255 R2W " & 1943 Resurvey

B.T.s as follows -

20" Now 24" I. Cedar N.  $11\frac{3}{4}^{\circ}$  E. 52 $\frac{1}{2}$  ft.  
Now 5 Tump - scribe visible on  
unhealed blaze.

12<sup>th</sup>? Now 21" I. cedar S.  $63^{\circ}$  E. 74 $\frac{1}{2}$  ft.  
2 live - shows partial scribe marks on  
nearly healed blaze. we mark.

New B.T. -

18" I. Cedar N.  $84^{\circ}$  E. 61 $\frac{3}{4}$  ft.  
MKd. "T255 R2W 57 CS BT"

This cor. lies on very precipitous  
S.W. slope approx. 40 ft. N. of  
Top of 80 ft. Bluff course  
N.W. & S.E.

August 3, 1966  
FILED  
RECEIVED

U.R.T.  
J.B.  
J.H.

*J.R. Tracy*

AUG 3 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

#72-T25-2W  
#84-23

\*

O.K. J.T.W. TB

C.S. File No.

54/27-161