

Review $\frac{1}{4}$ cor. 520/521 T245R1W
Fd. 1961 CS BRASS cap in place
& New & O.B.T. 25 follows - See Ren. #8
Orig. Now 38" FIR N. $14\frac{1}{2}$ " W. 29° ft.
2 live - shows SCAR - other O.B.T. gone
10" Hemlock N. 8° E. 13° ft.
2 live - Blaze healing - The
Yew B.T. To N.W. Now Broken off
Just above "BT" scribe - we
M.K. new B.T. -

15" Hemlock S. 82° W. 43 $\frac{1}{2}$ ft.
M.K. " $\frac{1}{4}$ 520 CS BT"

This cor. Lies approx 500 ft.
East of SCARED MAN access
Road & at S.W. cor. of
cutoff unit in Sec. 21.

May 28, 1970

VRT
VDP

A. R. T. Ray

O.V.
J.W. Co.

#105 ✓

C.S. File No. 54/27-195