

Renew Township Cor R1W ⁷²³ ⁵³⁶ / ⁵¹ / ⁵⁶ R1E

Ed. 1922 G.L.O. Brass cap on 3" I.P.
out of ground & C.B.T.S as follows -

Orig. 14" Now 22" Fir N. 60° E. 17 ± ft.

2 live - shows good scar - Tagged
Orig. 35" Now 40" Fir S. 40° E. 39 ± ft.

2 live - shows good scar - Tagged
Orig. 40" Now 46" Fir S. 34 1/2° W. 31 ± ft.

2 live - shows good scar - Tagged
1922-8" Now 8" Fir N. 2° W. 41 ± ft.

Now 5" Dog-Record N. 8° W. - scribe visible
on unhealed blaze - we Reset

G.L.O. Brass cap in proper place
& M.K. New B.T.

28" D. Fir North 44 ± ft.

Mkd. "T235 R1W 536 DCS BT"

This cor. lies approx. 100 ft. west
of access road from China Creek.
on very steep west slope.

April, 15, 1970

VRT
JGH
VDP

VR Tracy

o.k.
J.D.

#1-T23-1W
#2-T24-1W #3-T23-1E

C.S. File No. 54/27-201