

233/534 T235  
Renew Sec. Cor. 54/53 T245 RIW

Fd. O.B.T.s as follows -

ORIG. 30" FIR N. 38° E. 13 1/2 ft

Now Decayed stump - with scribe visible.

ORIG. 30" NOW 34" FIR S. 27° E. 62° ft.

2 live - shows good scar - we tag.

ORIG. 30" NOW 34" FIR S. 8° W. 23 1/2 ft.

2 live - Record 19 1/2 ft. - shows scar - we tag.

ORIG. 30" NOW 35" FIR N. 2° W. 19 1/2 ft.

2 live - Record 23 1/2 ft. - open - scribe visible

We do not find cor. stone - 2nd cor.

point set 1" I.P. & BRASS cap MKd

COUNTY SURVEYORS OFFICE 1970

T235 533/534  
54/53 T245 RIW" & MK.

New B.T.s -

6" D. FIR N. 52° E. 21 1/2 ft

Mkd. "534 CS BT"

13" D. FIR N. 62° W. 22 3/4 ft.

Mkd. "T235 RIW 533 CS BT"

This cor. lies on very steep

southerly slope approx. 50 ft.

FROM S. edge of logging Access Rd.

April 16, 1970

#2 - T23 - 1W

J. R. RATHWAY

VRT

JGH

UDB

D.W.

J.W. 19.

C. S. File No. 54/27-202