

Fd. T245 RIW

WITNESS COR TO $\frac{1}{4}$ $\frac{526}{335}$

BRASS CAP BENT OVER BITS BURIED
but still alive - we STRAIGHTEN CAP
& REscribe BITS - Set 6' steel fence
Post along side BRASS CAP - Metal
Locator indicates I.R. of TRUE
COR. point still in place under
Road Fill - See Ren. # 65

April 13, 1970

~~V.R.T. Ray~~

VRT
JGH
VAP

O.K.
JGH

DIETZGEN NO. 388-6

CS 54/27 - 201