

Renewal # 2

27/26

7295 R.W.

Found

16" D. Fir - Now 24" N33E 76°
Faces Badly Burnt - Scribe 1/2
1/5 other Wks Not 1/2 scribe

No trace of NW BT or cor stone
Due to skid Rd.

Renewal

Set Brass cap at 1/2 cor W.K.D.

county surveyors office

7295 R.W.

327 / 526

1970

DIETZEN NO. 385-6

New Bearing Tree


12" cedar 570W 47°
scribed 1/2 527 CS BT

Blazed & Rescribed

24" D. Fir N33E 76°
scribed 1/5 26 CS BT

8-26-70

~~Handwritten signature~~



86

- 5 File No. 54/27

24