

Revue $\frac{1}{4}$ $\frac{521}{528}$ T245 R2W

Fd. O.B.T. 25 Follows -

orig. 16" Now 18" FIR S 20° E, 16⁵ft

Now Decayed stump - open & find

" $\frac{1}{4}$ 5" scribe & Reverse - NO

Trace other O.B.T. - Weyerhaeuser

Reference Trees Now Burned

Stumps.

2^d cor. point set 1" I.P. & Brass

cap MKd. "COUNTY SURVEYORS

OFFICE 1969 T245 $\frac{1}{4}$ $\frac{521}{528}$ R2W"

There being no trees or

solid stumps available, we

set 2 $\frac{3}{4}$ " x 30" I.R. North 10° ft.

and 2 $\frac{3}{4}$ " x 30" I.R. West 20° ft.

25 Reference to $\frac{1}{4}$ cor.

This cor. lies in old

clear cut unit in Greasewood.

also set 6° ft. steel fence

post alongside Brass cap.

August 15, 1969

V.R.T.

J.G.M.

V. R. Tracy

#63

C.S. File No.

D.M.
J.V.M.A.
57/27-247