

530/529
531/532

Renew Sec. Cor. T245R2W

Fd. 1951 Cad. BRASS in place 25

Determined From Remaining B.T.

1951-48" FIR S, 74° E. 165 ft

sawed STUMP - Fragmentary SCRIBE on

BURNED BLAZE - Rescribe "T245R2W 532

CS BT" - MK. New BT -

16" Hemlock S, 21° W. 105 ± ft.

Mkd. "T245 R2W 531 CS BT"

Fd. Weyerhaeuser Ref. - 2 48"

FIR Stump S, 77° W. 42 ± ft.

This also orig B.T. NO SCRIBE Fd.

Badly BURNED - This COR Lies

ON Bench IN Dense FIR. Reprod,

greasewood & vine maple BRUSH.

August 21, 1969

U.R.T.
J.G.H.
U.D.P.

V.D. Tray

0.4 m
1.3

*67

C.S. File No. 54/27-252