

Renew $\frac{1}{4}$ cor 530/529 T245 R2W

Fd. O.B.T. 25 fo Now 5 -

ORIG. 12" Now 15" Hemlock S. 75° E. 34³ ft.

Now Stamp - Scribe MKs visible -

we find hole where N.W. O.B.T.

would have been. - at cor. point

set 1 "I.P. & BRASS cap MKd" COUNTY

SURVEYORS OFFICE 1969

T245 $\frac{1}{4}$ 530/529 R2W" - set

6' steel fence post along side -

MK. Now B.T.

40" D. FIR N. 45° W. 151⁵ ft.

Mkd. " $\frac{1}{4}$ 530 CS BT"

There being No Trees in

Sec. 29 we set $\frac{3}{4}$ " IR. N. 70° E.

15² ft. FROM $\frac{1}{4}$ COR. This cor.

Lies on moderate changing to

steep Northerly slope.

August 21, 1969

V.R.T.

J. G. H.

V.R.P.

V.R. Tracy

O.K.
J.W.B.

#68

U.S. FILE NO.

54/27-253