

Renew Sec. Cor. ^{R2W} 512 | 57 R1W T245
513 | 518

Fd. O.B.T.S 25 Follows -

ORIG. 24" Now 30" FIR N, 75° E, 17²/₃ ft,

Dead - BARK scribe visible - Poor cond.

ORIG. 30" Now 34" FIR S, 81° E, 19²/₃ ft,

Dead - Fragmentary BARK scribe visible.

ORIG. 32" Now 36" Hemlock S, 75° W, 30²/₃ ft,

2 live - scribe MKs, visible on unhealed

Blaze - We Rescribe - "T245 R2W 513 CS BT"

ORIG. 20" Now 24" FIR N 61° W, 36²/₃ ft,

Now snag - BARK scribe visible - ^(Record, 33²/₃ ft) 2+

Cor. point set 1" IP & BRASS cap

Mkd. COUNTY SURVEYORS

OFFICE 1969 T245 R2W

^{512 | 57}
513 | 518 R1W" & MK New B.T.S -

16" Hemlock N, 46° E, 30²/₃ ft,

Mkd. "T245 R1W 57 CS BT"

10" Hemlock N, 6° W, 22³/₃ ft,

Mkd. "T245 R2W 512 CS BT"

22" Hemlock S, 43° E, 59⁵/₃ ft,

Mkd. "T245 R1W 518 CS BT"

This cor. Lies on steep Northerly
Slope 90 ft. S. of creek

course E,

Sept 3, 1969

VRT
JGH
VDP

#81-224 VDP, Tra #

C.S. File No. 5222-25
P.W.
2019