

Renewal

511 | 512
514 | 513

T315 R2W

Found:

Stone at sec cor also 2" Iron Pipe

8" Fir N 37° 50' W 21' 0"

No Trace of this tree

OBT'S

24" Pine Now 28" S 24 W 47' 0"
Shows good Scar

20" Oak Now Dead: S 75 E 4' 0"
Faint Scribe Marks Visible

30" Fir Now 45" N 35 E 29' 0"
Bark Scribed "T315 R2W S12 CS"
"B7"

Renewed:

Set Brass cap at sec cor MKD.

County Surveyors Office

T315 R2W

511 | 512
514 | 513

1966

New Bearing Trees

9" D. Fir S 5 E 22' 5"
Scribed T315 R2W S13 CS RT

12" D. Fir N 28 W 8' 0"
Scribed T315 R2W S11 CS RT

This cor is 2' North of Fence Cor, Running East, West and South.

(Renewal # 7) * * * * *

7-15-66

[Signature]

*54

O.M. J.W.B.

U.S. File No. 54/28-15

DIETZGEN NO. 385-B