

Renewal

27/26
54/25

T31S R2W

Found:

Pieces of Probable cor Stone at cor.
 ORTS
 12" Pine Now 54g N23 E 70°
 2 End This bearing to cor N19° E
 Scribe visible "15" "26" "17"
 18" Fir Now 54g S 79 E 60°
 opened for scribe "2"
 15" Laurel Now 20" S 38 W 54°
 Rotten Face
 10" Pine Now 44" N 65 W 12°
 Scribe visible 31S R2W S27 BT

Renewed:

Set Brass cap at Sec cor 1/4th
 County Surveyors office
 T31S R2W

527 | 526
 554 | 515
 1966

NEW Bearing Traces

9" Laurel S29 1/2 E 7°
 Scribed T31S R2W S 35 CS BT
 10" D. Fir S31 W 91°
 Scribed T31S R2W S 34 CS BT
 8" D. Fir N86 E 15°
 Scribed T31S R2W S 26 CS BT

6-29-66
~~J.P.M.~~
~~T.H.D.~~
 T.C.C.

D.K.S.W.B.

X 64

C.S. No. 54/26-25

DIETZGEN NO. 386-6