

Renewal 535 536 T315 R2W

Fordi:

18" D. Fir NOW 24" N73E 27⁷

opened Tree for Service "4"

18" D. Fir NOW 24" S40W 27⁷

Tree shows good Scar.

No Trace of Stone at cor.

Renewed

Set Brass cap at $\frac{1}{4}$ cor NW^{1/4}
county surveyors office

T 315 R 2 W

$\frac{1}{4}$ 535/536

1966

Relazed + Rescribed

24" D. Fir N73E 27⁷

Scribed $\frac{1}{4}$ 536 CS BT

Bluff Bear N40W about
800

7-21-66

[Handwritten signature]

* #75-1

O.K. J.W.B.

C.S. File No. 54/28-33

DIETZGEN NO. 385-6