

Renewal

S13/S18
524/519 T315 R2-1W

Found:

Stone at Sec cor 14x10x8

19" B. Oak N42E 86⁵
(No trace of this tree)

20" B. Oak N45 1/2 W 74²
opened for scribe "3" "BT" (Bottom)

I find this bearing to be N75 1/2 W
20" Laurel N41" S56 W 17⁸
No scribe visible

10" Fir S10 E 99²
(No trace of this tree)

Renewed

Set Brass cap at Sec cor MFD
county surveyors office.

T315

R	<u>S13/S18</u>	R
2	<u>524/519</u>	1
W		W

1966

New Bearing Trees:

24" Cedar N45 1/2 W 11²
Scribed T315 R2W S13 CS BT

19" D. Fir N42 1/2 W 22⁹
Scribed T315 R2W

10" D. Fir S45 E 39¹
Scribed T315 R1W S19 CS BT

Re Blazed & Re scribed

24" Laurel S56 W 17⁸
Scribed T315 R2W S24 CS BT

(Renewal # 11) T315 7-12-66

*20-R1W
*490 RR J.W.B. C.S. No. 54/28-¹¹¹⁰ BT
CS

DIETZEN NO. 385-6