

Renewal 535 | 536 7313 R2W  
52 T32

Found:

Stone at sec. cor. No Marks  
ledgible

30" D. Fir NW 38° N 45W 5<sup>3</sup>  
Shows good scar.

16" D. Fir N30E 19<sup>0</sup>

This tree down with burnt  
Face. Ser. bc Marks visible  
'B' and 'S'

I Find Bearing to be N 65E 19<sup>0</sup>  
Renewed:

Set Brass cap at sec. cor MAD,  
county Surveyors office

7313 R2W

535 | 536

52

T32 S

1966

New Bearing Tree

30" D. Fir N 27E 55<sup>0</sup>  
ser. bed 7313 R2W 536 CS BT

7-21-66

*[Handwritten signature]*

✓ #74-T31-2  
\* #14-T32-2

C. S. File No. 64/28-48

DIETZGEN NO. 386-6