

Renewal 12/4 T315 R2W

Found

18" Fir Now Stump N68 1/2 W 5 1/2

BT scribe visible

No trace of orig. B.T.S.

Good 1/2" x 2 P.P. at 1/4 cor.

Renewed:

New Bearing Trees

8" Cedar S 71 W 8 2

Scribed 1/5 1/4 CS BT

9" Cedar S 59 E 25 2

Scribed 1/5 1/5 CS BT

This cor lies by East & West Fence line.

1/4" South of Fence line

7-29-66

*[Handwritten signature]*

Renewal #1/4

#13

OK J.W.B. C.S. No. 54/28-54

DIETZEN NO. 385-B