

Renewal

$\frac{53}{510} | \frac{52}{511}$

T315 R2W

20" Fir Now stump N45W 58°

12" Fir Now stump S79E 53°
opened stump "BT"

15" Fir Now 21" S31W 87°
Shows good scar

5" Oak Now 10" N38E 29°
Scribe visible "2" "CS"

Renewed

Set Brass cap at Sec cor M&A
County Surveyors office

T315 R2W

$\frac{53}{510} | \frac{52}{511}$

1966

New Bearing Trees

7" D. Fir S45E 31°

Scribed T315 R2W S11 CS BT

16" LAUREL S N52W 38°

Scribed T315 R2W S3 CS BT

16" D. Fir S51W 17°

Scribed T315 R2W S10 CS BT

(Plants #0/#23)

8-16-66

~~Handwritten signature~~

#99

C.S. File No. 5428-76

DIETZEN NO. 385-5