

Renewal SE corner only T315 R3W

Found:

10" W. Fir now 10" N55W 60^S

Shows good scar,

11" Cedar now 14" N40E 68^S

Scar visible "S1 BT"

15" W. Fir now stump S16W 28^E

opened for Scar "T32"


24" W. Fir now down S14E 7^E

Also $\frac{3}{4}$ " E. P.R. Bent ^(Pen #41) over
under small log.

Renewed

Set Brass cap at Sec cor MKD,
County Surveyors office

T315



Reblazed & Rescribed

14" cedar N40E 68^S

scribed T323 R3W S1 CS BT

No other trees available, this
cor lies just on south side of

Small Ridge Running E-W 8-30-66

* T32-5
#114 T31-2
#114 T31-3

C.S. File No. 54/28-07-11
T.C.C.

DIETZGEN NO. 385-6