

Renewal

$\frac{56}{57} / 55 / 58$

T315 R2W

Found

Slats Stone at sec cor.

40" D. Fir Now 48" N34E 178  
Shows good scar

12" Hemlock Now 564W 178  
Scribe visible "3" "2" "7"

7" W. Fir Now 17 N11W 192  
Shows good scar

12" Maple Now down 564W 13±

Renewed:

Set Brass cap at sec cor.

County Surveyors office

T315 R2W

$\frac{56}{57} / 55 / 58$

1966

New Bearing Trees:

9" Hemlock 582E 349  
Scribed T315 R2W S7 CS BT

Rescribed:

20" Hemlock 564W 178  
Scribed T315 R2W S7 CS BT

This cor lies 100± FT West of  
Notched creek

9-19-66  
J. J. [unclear]  
J. J. [unclear]  
C. J. [unclear]

#118

\* O.K. J.W.B.

U.S. File No. 54/28-97

DIETZGEN NO. 388-6