

Renewed 58/59 T3AS R2W

Found:

20" Pine New Snag S 60 E 17'

Scribe visible '59 137"

30" Cedar New 30" S 90 W 59'

Shows Scar, Almost Dead.

Also 30 x 18 x 5 Stone Mark

With X & 1/4 on W Face

Renewed:

Set Brass cap at 1/4 cor Mark
county Surveyors office

T3AS R2W

1/4 58/59

1966

New Bearing Trees

17" Cedar S 74 E 76'

Scribed 1/4 59 CS BT

19" Cedar S 85 W 72'

Scribed 1/4 59 CS BT

This cor. lies on Ranty East Slope
Next to Edge of timber Running
about E & W

9-7-66

~~JWB~~
~~SWD~~

TC

54/28-107

DIETZEN NO. 385-6

3113
* O.K. J.W.B.

C.S. R. R. 54/28-107