

Renewal

524
525

7315 R6W

Found

2. Rod at $\frac{1}{4}$ cor.

8" Hemlock now 8" N56W 65L
Scribe visible $\frac{1}{4}$ S 521 BT

36" P. Fir now stump S70W 66S
Scribe visible 7315 R6W $\frac{1}{4}$ S 525 BT

Renewed!

Set Brass cap at $\frac{1}{4}$ sec cor M.K.
county surveyors office

7315 R6W

$\frac{1}{4}$ 524
525

1965

New Bearing Tree

7" W. Fir N 82 E 34 L
Scribed $\frac{1}{4}$ S 29 CS BT

No Trees in S25 to scribe

This cor lies on steep North
slope, about 200' South of
Creek.

Location Tag on stump North side
of logging Rd. about 300' North
of $\frac{1}{4}$ cor.

9-30-66.

J.M.G.
J.W.B.
J.2.10.

(Renewal #63)

#93
XO

O.K. J.W.B.

C. S. File No.

54/31-10