

Renewal 51 56  
S 12 | 37 T315 R546W

Found  
16" Fir Now 36" S4E 11 9  
Tree had been opened & burnt  
opened dome but no scribbing visible

14" Fir Now 1200 S70W 7 9  
old rotten snag has fixed face  
with faint "S" & other marks. Scribbing  
done with very fine scribe at  
Haife.

12" Fir Now Downsag North 6 6  
Has old axe work no scribe  
visible.

No Trace of 8" V. Maple  
"Resurvey 1878"  
By ring count on 36" Fir it  
places this cor at 1878. Also  
call on small creek at 16 5  
North of cor hits very good

Renewal:

Set Brass cap at Sec. cor MITA  
county surveyors office

T315  
R 51 | 36 R  
S 512 | 37 S  
W W  
1966

New Bearing Trees

14" Maple N B E 31 0  
scribed T315 R5W S6 CS BT

12" Maple N 58 W 48 3  
scribed T315 R5W S1 CS BT

#102-T315  
\*89 O.W. J.W.B. - OVER - ↓ c.s. 54/38"

DIETZGEN NO. 385-6

13" Maple S 84 W 36<sup>0</sup>  
Scribed T 31 S R 6 W S 12 CS BT

Noted & Measured  
36" D. Fir S 4 E 11<sup>9</sup>  
Scribed T 31 S R 5 W S 7 CS BT

10-3-66  
JMO  
FMJ  
C.H.S.  
J.D.H.

No 7 Found ds.  
(1888 Resurvey)  
1/6 12/7

FILED  
RECEIVED

OCT 5 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.