

Renewal 34/35 731S R6W  
5/2 731S R6W

Found 0 BT's

29" D. Fir	N 32" S 41 E	77 <sup>9</sup>
shows good scar		
30" D. Fir	N 54 W 53 SW	38 <sup>3</sup>
scribe visible 2" S		
20" D. Fir	N 54 W 34" 45 W	31 <sup>9</sup>
opened for scribe '87'		
4" D. Fir	N 57 E	28 <sup>1</sup>
No trace of this tree		

Renewed:

Set Brass cap at sec cor. MND  
county Surveyors office  
731S R6W

534/535  
S3/32  
732 N6W  
1966

New Bearing Tree

15" D. Fir	N 20 W	23 <sup>8</sup>
Scribed 731S R6W S3 + CS BT		
24" D. Fir	N 43 E	30 <sup>5</sup>
Scribed 731S R6W S35 CS BT		
16" D. Fir	S 25 W	18 <sup>0</sup>
Scribed 732S R6W S3 CS BT		

10-11-66  
*[Signature]*  
C.S.

489-32-6  
111-T31-6  
\* O.W. J. W. 13

C. S. File No. 54/31-22

DIETZEN NO. 385-6