

Renewal

27/26
34/35

T315 R6W

Found

OSTE

16" D. Fir NW 29" S. 90 E 11 2
Found Part Sec of "79" "3"

16" D. Fir NW 21" S 65 W 31 0
Shows good scar

10" D. Fir NW 21" N 66 W 27 L
Shows good scar

No Trace of NE Tree

Renewal

Set Brass cap at S corner. MAD
County Surveyors Office

T315 R6W

527/526
939/535

Reblazed & Rescribed:

29" D. Fir S 30 E 11 2
Rescribed T315 R6W S 35 C 3 BT

New Bearing Tree

10" D. Fir N 39 E 25 E
Rescribed T315 R6W S 26 C 3 BT

10-12-66

J. M. O.
P. H. G.
C. F. S.

DIETZEN NO. 388-6

* #109
O. H. J. W. B.

C. S. File No. 54/31-25