

Renewed

533
54

7313 R6W
7323 R6W

Found

12" Fir now down & rotten S55W 33
Found old Reverse Scribe Marks

8" Fir now 11" N60E 31 1/2
Shows very good Face

Renewed:

Set Brass cap at 1/4 sec cor mark
county surveyors office

7313 R6W

533
1/4 54

7323
1966

New Bearing Tree

26 D. Fir S88W 19 1/2
scribed 1/4 54 CS BT

PK Nail in Rock West 36

This cor lies on very steep North
slope - 25 FT West of Rocky
Point about 124 FT High.

10-25-66

JMB
CFS
ERW

#90-732

#121 O.K. J.W.B.

C.S. File No. 54/31 1/2