

Renewal

3/2
10/27

T31S R9W

Found: orig BTs

29" D. Fir Now 26" N12E 337
Shows good scars but burnt face
Faint scribe marks visible

18" D. Fir Now 20" S32E 178
Scribe visible NBT

16" D. Fir Now stub S26W 241
Shows good scar

18" D. Fir Now 28" N49W 901
Shows good scars

Renewed

Set Brass cap at sec cor MKR
County Surveyors office

T31S R9W

43/52
3/10/51

19167

New Bearing Tree

36" D. Fir S 5 W 251
Scribed T31S R9W 3rd cor BT

2-21-63
JMG
BAG
CRS

DIETZGEN NO. 385-6

*860

C. S. File No. 54/327