

Renewal 533/534 T31S R9W

Found:  
Orig Tree

8" Yew Cove Tree  
Scribe Visible "533" "534"

18" D. Fir Now 22" S12W 45°  
Burst Face

8" D. Fir Now Down N38E 21°  
Tree Rotted

Renewal

Set Brass Cap on North Side  
of Cove Tree MAB

County Surveyors Office

T31S R9W

1/4 533/534

1967

New Bearing Trees

7" Red Oak S21E 95°  
Scribed by 534 CS RT

13" Laurel S84W 59°  
Scribed by 533 CS RT

3-15-67

*[Handwritten signature]*

X-89  
D. K. J. W. B.

C. S. File No. 54/32-35

DIETZGEN NO. 388-6