

Renewal

RP
1917

T313
T323

R
9
W

Found

Brass cap MCD

US General Land Office

RP
1917

60" D. Fir New stump NG15 30°
opened for Scribbling "BT"

29" D. Fir New snag 376W 16°
shows scar

Renewal

New Bearing Trace:

8" Yew wood S 61 W 77°
Scribed RP CS BT

9" D. Fir N 30 W 59°
Scribed RP CS BT

Note:

Logging Rd Bears North 65°

Rise 1917 East of

54/63

3-15-67

~~RP~~
~~BT~~
~~CS~~

* 091
* + - D3R. S. W. B.

C. S. File No. 54/32-37

DIETZEN NO. 388-B