

Renewal

30/29  
31/32

T31S R9W

Found:

No Trace of stone  
orig tree

10" D. Fir Now Dead S 15 W 38±  
scribed for Scriber "31 T31S R9W"

No Trace of other Bearing Trees

Renewal

Set Brass cap at Sec. 400 M&D  
County Surveyors office

T31S R9W

530/529  
531/532

1967

New Bearing Trees

6" Yew S 35 W 57±  
scribed T31S R9W 531 c.s. BT

8" D. Fir N 44 E 42±  
scribed T31S R9W 529 c.s. BT

6" Pine oak S 55 E 58±  
scribed T31S R9W 522 c.s. BT

30" Fir stump N 70 W 27±  
scribed T31S R9W 530 c.s. BT

Note this cor. lies about 150' north  
& 100' west of small creek.

Also about 300' south from Rd. on  
Ward Park, near creek.

Yellow Tag on Road 3-16-67

~~531/532~~  
531/532  
531/532

O.K. J.W.B.

C.S. File No. 31/32-39

DIETZGEN NO. 386-S