

Renewal

532/533

T315 R9W

Found:

orig. ~~mark~~
No trace of stone at $\frac{1}{4}$ cor

36" D. E. Now 42" S. S. 2 E 17 E
opened for sample "S"

18" D. E. Now 29" N 85 W 62 E

Shows good seam
I find this bearing to be N 85 W

using 2 Dist. & Bearing 3 Round

Renewal

Set Brass cap at $\frac{1}{4}$ cor MKD.

County Surveyors Office

T315 R9W

$\frac{1}{4}$ 532/533

1967

All Bearing Trees in good
Shape

FILED

3-16-67

RECEIVED

[Handwritten signature]

MAR 16 1967

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

[Handwritten initials]
O.K. J.W.B.

C.S. File No. 54,320

DIETZGEN NO. 388-B