

Renewal

50/59
517/516

T315 R9W

Renewal # 12

Four d.
(orig. BT's)

16" D. Fir Now stump N42E 6'
Stump has been spaced '59' T315 R9W

24" D. Fir Now stump S90E 23'
Shows good saw

No trace of SW BT

I.P.P. at cor.

Renewed

Along side I.P.P. sat Brass cap MKD
County Surveyors office

T315 R9W

50/59
517/516

1967

New bearing trees

9" W. Fir N47E 55'
Scribed T315 R9W S9 CS BT

9" W. Fir S2E 10'
Scribed T315 R9W S16 CS BT

3-21-67

X 93

O.K. J.W.B.

C.S. File No. 54/32-47

DIETZEN NO. 388-B