

Renewal 9/10
(Renewal *22) 16/15 T 315 P 9 W

Found:
3/4" J.P.R.
orig pts
32" D. Fir now 38" S 39 E 52°
Shows good scar
I find marks dist to be 45°
30" D. Fir now 50" S 35 W 30°
Shows good scar,
Renewed trees:
30" D. Fir (up root) S 71 W 25°
Scar visible T 315 P 9 W
No trace of Renewal SW BT
Renewal:

Alongside J.P.R. set Brass cap 1967
County Surveyors Office
T 315 P 9 W

59/510
516/515
1967

New Bearing trees

18" D. Fir S 2 W 34°
Scribed T 315 P 9 W S 16 CS BT
18" D. Fir N 4 E 45°
Scribed T 315 P 9 W S 10 CS BT
6" W. Fir N 19 W 79°
Scribed T 315 P 9 W S 9 CS BT

Note:
creek Bears north 100°
3-21-67

~~W.C.S.~~
W.C.S.

DIETZEN NO. 388-6

X 794
O.K.J.W.B.

C.S. File No. 54/32-48