

RENEWAL

529 528 T315 R9W
532 533

FOUND: NO TRACE OF CORNER STONE

28" D FIR NOW 28" S10W 139 FT
SHOWS 2 GOOD FACES

10" LIVE OAK NOW 11" S65E 35 2 FT
SHOWS GRIBING OF: "S33 T315 R9"

RENEWAL:

SET: BRASS CAP AT CORNER M.K.D.
COUNTY SURVEYORS' OFFICE
T315 R9W

529 528
532 533

1967

RESCRIBED:

10" LIVE OAK NOW 11" S65E 35 2 FT
SCRIBED T315 R9W S33CS BT

NEW BITS:

36" D FIR N4W 40 2 FT

SCRIBED: T315 R9W S28CS BT

26" D FIR N76W 30 2 FT

SCRIBED T315 R9W S28CS BT

4-6-67

#100
X00 J.W.B.

FWJ
C.S. File No. 54/32-64

DIETZGEN NO. 385-S