

Renewal

R.P.

T 31 S R 9 W  
T 32 S R 9 W

Found:

Car Tree Now Stab 72" S. Pine  
Scribe Visible R.P. BT on  
North East side

Orig Tree

30" D. Fir Now 37" N 70 E 38"  
Scribe Visible R.P.

(Now BT)

30" D. Fir Now Splintered Stab SWW 20"

Renewed

Set Brass cap on North side of  
S. Pine Stab. M.R.P.

County Surveyors office

T 31 S R 9 W

R.P.

T 32 S R 9 W

1967

New Bearing Tree

9" Lateral Scribed R.P. CS BT N 41 W N 0

Note:

This R.P. lies 142' East  
of

S 3 1/2 T 32 S R 9 W.

4-10-67

~~Handwritten signature~~  
1967

T 32 R 9 W

121

\*

C. S. File No. 54/32767

DIETZEN NO. 385-6