

Renewal

525/530
536/531

T315 R10-9W

Found

10" D.E.V. NOW 28" N 52 1/2 E (Rec. 1520) 206 1/2
Shows good Scar

11" D.E.V. NOW 24" S 45 E 37 1/2
opened earlier "R 9" visible

8" D.E.V. NOW 19" N 77 W 19 1/2
Shows good Scar

No Trace of S.W. Tree
Renewal:

Set Brass cap at sec cor NAD,
county Surveyors office

T315

R 525/530 R
10 536/531 9
W W

1967

New Bearing Trees:

14" D.E.V. N 63 E 78 1/2
Scribed T315 R9W S30 CS RT

10" D.E.V. S 67 1/2 E 51 1/2
Scribed T315 R9W S31 CS RT

17" PINE S 43 W 18 1/2
Scribed T315 R10W S36 CS RT

5-1-67
[Signature]
JCS

0/35 O.K. J.W.B

C.S. File No. 54/32-75

DIETZGEN NO. 388-6