

Renewal

S18
S19

T315 R9W

Found:

orig. Trees & Renewal #17

24" D. Fir NW 217 N28E RB²
Tree appeared earlier Scars Marked Visible

26" D. Fir NW 216" Sagg S24E (Recs. W) 58²
Tree shows good scars

No Trace of Iron P.P. Set in 1961
Renewal #12

Renewal

Set Brass cap at $\frac{1}{4}$ cor MKR
County Surveyors Office

T315 R9W

$\frac{1}{4}$ S18
S19

1967

Alow Bearing Tree

8" Cedar S50E 19^o
Scribed $\frac{1}{4}$ S 19 as AT

Note:

This cor lies about 250^o East
of steady creek

S-93-62
~~JMB~~
~~JMB~~
JMB

O.K. J.W.B.

C. S. File No. 54/32 -76

DIETZGEN NO. 388-6