

Revised 517/516 7315 R9W  
(Revised #14)

Found

36" D.E. - NW 1/4 - 517 176E 19<sup>3</sup>  
Badly Buried Area No good Scribe left  
Point "BT"  
12" D.E. - NW 1/4 - 115E 27<sup>3</sup>  
Scribe visible "BT" "1/4"

No Trace of Iron P.R., This area  
being heavily logged.

Remarks:

Set Brass cap at 1/4 cor MKD  
County Surveyors office

7315 R9W


1/4 517/516

1967

Now Bearing True

13' Hemlock 554W 73<sup>3</sup>  
Scribed 1/4 S 17 AS BT

J-5-67



\* 1/1

O.K. J.V.V.B.

C.S. File No. 54/32-79

DIETZGEN NO. 385-6