

Renewal

RP

T315
T325 RW

Found

18" Chingapio New 18' base N45E 38°
Bearing no service marks

8" Yew New 8" 527W 19L
First service marks not redigible

Bears cap at RP MKP,

General land office

RP
1917

This RP lies 260° East of

See con of $\frac{T315}{55.54}$ $\frac{T325}{T325}$

DIETZGEN NO. 3886-6

Renewal

New Bearing tree

58" P.P. S58E 23°
Scribed RP CS BT

8" Chingapio N83W 29°
Scribed RP CS BT

5-12-67

[Handwritten signature]
J.C.C.B.

#18-132

O#147

O.K. J.W. 13

C.S. No. 54/32-86