

Renewal

514  
514

7315 R9W

Found:

Part of Stone  $\frac{1}{4}$  cor

16" D. Fir Now <sup>22</sup> S 30 E 17  $\frac{3}{4}$   
opened for scribing "44" "45"

30" D. Fir Now <sup>36</sup> N 25 E 5  $\frac{3}{4}$   
shows good shape

Reviewed:

Set Brass cap at  $\frac{1}{4}$  cor 1740,  
County Surveyors office

7315 R9W

$\frac{1}{4}$   $\frac{514}{314}$

1967

New Bearing Trees:

7" cedar S 22 E 43  $\frac{3}{4}$   
scribed  $\frac{1}{4}$  S 14 CS BT

10" cedar N 39 E 14  $\frac{3}{4}$   
scribed  $\frac{1}{4}$  S 11 CS BT

10-16-67

~~DMG~~  
~~BT~~  
~~CS~~

\*<sup>o</sup> O.K. J.W.B

C.S. File No.

54/32-92

DIETZEN NO. 385-6