

Renewal 26/25 T315 R9W

Found

3/4" T.P.P. 18" under ground:

Orig. BT

D.F.'s Now Down N 70W 16 1/2"
opened for scribe Marks found "6"

#2 Renewal

42" Fir Now Down S 66 1/2 W 30
Scribe Marks visible but Ripped over

90" Fir Now Down N 19 1/2 E 19"
Scribe visible 25 1/4 S R5421 BT

#28 Renewal

6" D.F.'s Now 10" S 81 1/2 W 108"
I find this distance 117'

shows good scars,
No trace of S.F. P.T.

By using orig Tree, T.P.P. + 2 Down
Trees I Renew

Along side T.P.P. I set 8ms cap MAD

county Surveyors office
T315 R9W

1/4 526/525
1967

New Bearing Tree

4' Live oak N 48 E 39 1/2"
Scribed 1/4 525 CS BT

Note:
This cor line on N North
and Ad.

10-17-67
[Signature]

#57
* O.K. J.W.B.

C.S. File No. 54/22 94

DIETZEN NO. 385-6