

Renewal $\begin{matrix} R \\ 8 \end{matrix} \begin{matrix} S25 \\ W \end{matrix} / \begin{matrix} S30 \\ W \end{matrix} \begin{matrix} R \\ 7 \end{matrix} \begin{matrix} T315 \end{matrix}$

Found:

36" D. Fir NOW 48" S 25 W 30[±]
Bark Scribed $\frac{1}{4}$ S BT Faint

26" D. Fir NOW 32" S 85 E 30[±]
Shows old face opened for scribe "4" "5"

I Find This Bearing & Dist. to be
S 89 E 26[±]

Remarks:

Set Brass cap at $\frac{1}{4}$ cor MAD
County Surveyors office

7315
 $\begin{matrix} R \\ 4 \end{matrix} \begin{matrix} R \\ 8 \end{matrix} \begin{matrix} S25 \\ W \end{matrix} / \begin{matrix} S30 \\ W \end{matrix} \begin{matrix} R \\ 7 \end{matrix} \begin{matrix} W \end{matrix}$

1966

New Bearing Trees

13" D. Fir N 55 $\frac{1}{2}$ W 26[±]
Scribed $\frac{1}{4}$ S 25 CS BT

10" D. Fir S 63 E 36[±]
Scribed $\frac{1}{4}$ S 30 CS BT

12-25-66

*#69
#25-T31-8

O.K. J.V.V.B. U.S. File No. 54/36-6

DIETZEN NO. 385-6

**FILED
RECEIVED**

DEC 15 1966

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**